

Vehicle Inspection Report

Carried out by Peter



ABN: 37866074083

MVRL: 55738

Mob: 0402 408 936

Email: pjenkyns@optusnet.com.au

Website: www.sydneymotorsinspections.com.au

REPORT DETAILS

Date	08-02-22
Buyer	Alex
Phone	
Seller	Apex Used Cars
Phone	
Address	Caringbah
Make	BMW
Model	330d E90 Auto
Badge/ Series	6cyl 3.0L Turbo Diesel
Colour	Silver Grey
Comply Date	Jun-09
Build Date	Apr-09
Rego No	EPC 87B
Rego Exp Date	10-06-22
Kms Reading	134,088
Vin Number	WBAPR96010NJ73529
Number	AO1263367

Abbreviations

D/S Driver Side	P/S Passenger Side
D/S/F Driver's Side Front	P/S/F Passenger Side Front
D/S/R Driver's Side Rear	P/S/R Passenger Side Rear

Colour Codes

 Checked/Okay	 Minor Repairs Recommended	 Future Repairs Required	 Immediate Repairs Needed
--	---	---	--

ENGINE			OK	NO			Comments
1		Engine Idle	*				
1a		Engine Oil Condition	*				
2		Engine oil leaks	*				
3		Fumes/Smoke	*				
4		Engine Main Seals	*				
5		Rocker Cover Gasket	*	X			Rear of rocker cover has slight leak
6		Engine Sump Gasket	*				
7		Fluid Levels	*				
8		Engine Mounts	*				
9		Emission controls	*				
10		Drive belts & pulleys	*				
11		Fan (Electric)	*				
12		Hoses/Pipes	*				
13		Fuel system (injectors)	*				
14	NA	Camshaft timing belt (see below)	*				
15		Turbo/Intercooler	*				
16		Inlet Manifold leaks	*				
17		Engine noises	*				
18	NA	Compression Test	*				

NOTE: Usually, timing belts can't be physically checked as plastic covers need to be removed. You must refer to the manufacturer's specifications in order to confirm replacement times.

Additional Comments

AUTEL SCAN REPORT	Comments
Diagnostic Result (Error Codes)	
No error codes reported	

AUTO TRANS/GEARBOX			OK	NO			Comments
19		Operation	*				
20	NA	Clutch (Man)	*				
21		Inhibitor Switch (Auto)	*				

22	NA	Gear Linkages (Man)				
23		Gear Shifting (Auto)	*			
24		Mountings	*			
24a		Auto/Gearbox Fluid Condition	*			
25		Auto Pan Gasket	*			
25a		Fluid/Oil leaks	*			
26		Noises	*			
27	NA	Transfer Case (4x4 or AWD)	*			

Additional Comments

COOLING SYSTEM			OK	NO		Comments
59		Radiator & cap	*			
60		Hoses & pipes	*			
61		Water pump & fan	*			
62		Radiator coolant level	*			
63		Inhibitor/coolant concentration	*			Strong
64		Leaks	*			
65		Pressure Test	*			

Additional Comments

STEERING & SUSPENSION			OK	NO		Comments
73		Front suspension/shocks	*	X	X	P/S/F shock (starting to leak)
74		Rear suspension/shocks	*			
75		Wheel bearings	*			
76		Drive shafts, Boots, & Uni	*			
77		Ball Joints/ Tie Rod Ends	*			
78		Rack & Pinion/ Steering Box	*			
79		Sway Bar/Control Arm Bushes	*			

Additional Comments

BRAKES			OK	NO	Comments
--------	--	--	----	----	----------

80		Master cylinder/ booster	*							
81		Brake Pedal	*							
82		Brake callipers	*							
83		Hoses & pipes	*							
84		Front brake pads	*				60		% remaining	
85		Rear brake pads	*				70		% remaining	
86		Front Brake Rotors	*							
87		Rear brake rotors	*							
88	NA	Rear Wheel cylinders	*							
89		Hand brake	*							
90		Brake Fluid Moisture Content	*				<1%			

Additional Comments

TYRES & WHEELS		OK	NO			Comments					
91		Front Tyre Condition	*	×			D/S	20	P/S	30	% Remaining
92		Rear Tyre Condition	*	×	×		D/S	10	P/S	10	% Remaining
93		Spare Tyre (plain rim)						None	Run Flat tyres fitted		
94		Alloy Wheel Condition	*	×	×		Scraped				
95	NA	Rims/Wheel caps									

Additional Comments

EXHAUST SYSTEM		OK	NO			Comments					
66		Catalytic Converter Function	*								
67		Mufflers x 2	*								
68		Exhaust Manifold	*								
69		Exhaust Pipes x 2	*								
70		Tailpipe(s)	*								
71		Brackets/ Fittings	*								
72		Leaks	*								

Additional Comments

UNDERBODY			OK	NO			Comments
96		Sub frame/ members	*				
97		Mounting points	*				
98		Under floor panels	*				
99		Fuel tank & hoses	*				
100		Differential/Transaxle	*				

Additional Comments

ELECTRICAL SYSTEM			OK	NO			Comments
28		Charging System	*				14.1 Volts
29		Ignition system	*				
30		Ignition Barrel/ No of Keys	*				2
32		Battery Condition	*				
33		Battery Cables/Terminals	*				
34		Starter motor cranking	*				
35		Injectors	*				
36		Headlights	*				
37		Tail lights	*				
38		Blinkers	*				
39		Brake Lights	*				
40		Parking lights	*				
41		Number Plate Lights	*				
42		Hazard Lights	*				
43		Horn	*				
44		Power Windows	*				
45		Central locking/remotes	*				
46		Power mirrors	*				
47		Window wipers & washers	*				
48		Sunroof (softtop)	*				
49		Fog/driving lights (front/rear)	*				
50		Alarm (immobiliser)	*				

Additional Comments

AIR CONDITIONING			OK	NO			Comments
52		Operation	*				Cold
53		Condenser	*				

54	Compressor	*	Yellow	Orange	Red
55	Pipes/ Hoses	*	Yellow	Orange	Red
56	Gas	*	Yellow	Orange	Red
57	Belts	*	Yellow	Orange	Red
58	Leaks	*	Yellow	Orange	Red

Additional Comments

INTERIOR		OK	NO	Comments	
101	Seats (front/rear)	*	Yellow	Red	
102	Seat belts/mountings	*	Yellow	Red	
103	Headlining	*	Yellow	Red	
104	Interior lights	*	Yellow	Red	
105	Carpets (front/rear)	*	Yellow	Red	
106	Floor mats (front & rear)	*	Yellow	Red	
107	Door panels	*	Yellow	Red	
108	Door trims	*	Yellow	Red	
109	Floor/Kick panels	*	Yellow	Red	
110	Door handles (inner)	*	X	X	D/S/R door handle rubber (perished)
			X		P/S/R door handle rubber (slightly perished)
111	Rear boot	*	Yellow	Red	
112	Dash pad	*	Yellow	Red	
113	Glove box	*	Yellow	Red	
114	Headrests	*	Yellow	Red	
115	Rear view mirror	*	Yellow	Red	
116	Door locks/hinges	*	Yellow	Red	
117	Door rubbers	*	X	Red	D/S/F door rubber (small split)
118	Door warning light	*	Yellow	Red	
119	Window operation	*	Yellow	Red	
120	ABS Warning Light	*	Yellow	Red	
121	SRS Warning Light	*	Yellow	Red	
122	Dash warning lights/gauges	*	Yellow	Red	
123	Electric fan	*	Yellow	Red	
124	Heater/demister	*	Yellow	Red	
125	Radio/CD	*	Yellow	Red	
126	Aerial (guard/roof)	*	Yellow	Red	
127	Sound Equipment/Speakers	*	Yellow	Red	
128	Onboard computer (trip meter)	*	Yellow	Red	
132	Lights/blinkers	*	Yellow	Red	
133	Rear demister	*	Yellow	Red	
134	Cigarette lighter	*	Yellow	Red	
135	Bonnet release (cable)	*	Yellow	Red	
136	Petrol lid (auto/ manual)	*	Yellow	Red	
137	Boot release (auto/ manual)	*	Yellow	Red	
138	Steering Wheel (adjustable)	*	X	Red	Wear on top of steering wheel
139	Tool kit (Jack/Wheel Brace)	*	Yellow	Red	

Additional Comments

Additional Features		OK	NO			Comments
	Click here to see all features	*				

EXTERIOR			OK	NO			Comments
140		Bonnet/ Boot Struts & Locks	*				
141		Door Handles & Locks	*				
142	NA	Door Moulds					
143		Door mirrors	*				
144		Door pillars	*				
145		Windscreen (F & R)	*				
146		Windows & Trims	*				
147		Wiper rubbers (F & R)	*				
148		Chassis & Rails	*				
149		Inner guards	*				
150		Front grill	*				
151	NA	Roof rack (rails)					
152		Head lights	*				
153		Tail lights	*				
154		Blinkers	*				
155		Number plates	*				
156	NA	Tow bar (Tongue & Ball)					
157		Badges	*				
158	NA	Mud flaps (front & rear)					

Additional Comments

BODY & PAINTWORK		Ums	NO			Comments
159	D/S/F Guard	220				Prev. Respray
160	D/S/F Door	210				Prev. Respray
161	D/S/R Door	150				

162	D/S/R ¼ Panel	150				
163	Rear bumper bar					
164	Rear Boot/hatch	130				
165	P/S/R ¼ Panel	200				Prev. Respray
166	P/S/R Door	200				Prev. Respray
167	P/S/F Door	200				Prev. Respray
168	P/S/F Guard	150				
169	Front bumper bar		×			Paint chipped and grazed on centre of bumper
170	Front bonnet	130				
171	Front lower spoiler		×	×		Scrape marks underneath Paint marks on side c
172	Side skirts					
173	Roof	130				

NOTE: Paint Thickness is measured in micron units (Ums)

Additional Comments

Car has been lightly respray on the above panels
Paint thickness is only 70-80 microns thicker which indicates previous light scratch repairs
The quality of the paint repairs is excellent with no sign of fisheyes, paint runs, or scratch marks under the paintwork.

ROAD TEST		OK	NO	Comments					
174	Engine performance	*							
175	Exhaust smoke	*							
176	Transmission/ gearbox	*							
177	Differential/ drive train	*							
178	Steering/ suspension	*							
179	Braking/ pedal operation	*							
180	Speedo operation	*							
181	Cruise control	*							
182	Car Performance	*			Poor	Fair	Good	V.Good	Excellent
183	Engine	*			Misfire	Rough	Uneven	Even	Smooth
184	Acceleration	*			Poor	Fair	Good	V.Good	Excellent
185	Handling	*			Poor	Fair	Good	V.Good	Excellent
186	Ride	*			Soft	Hard	Normal	Smooth	V.Smooth
187	Overall condition for age/kms	*			Poor	Fair	Good	V.Good	Excellent

Note: Criteria is ranked for the vehicle make, model, age, and kms.

Additional Comments

Carlton NSW 2218
Email: pjenkyns@optusnet.com.au

www.sydneyautoinspections.com.au



Audio, Visual & Communication

Inputs

Aux Input USB Socket
MP3 Decoder

Bluetooth

Controls

Multi-function Control Screen - Colour

CD / DVD

CD Player
CD Stacker - 6 disc

Entertainment

Colour Display Screen - Front

Speakers

10 Speaker Stereo
Safety & Security

Airbags

Driver
Passenger
Head for 1st Row Seats (Front)
Head for 2nd Row Seats
Side for 1st Row Occupants (Front)

Seatbelts

Lap/Sash for 5 seats
Pretensioners 1st Row (Front)
Pretensioners 2nd Row (Rear Centre)
Pretensioners 2nd Row (Rear Outer seats)

Emergency

Brake Assist
Brake Emergency Display - Hazard/Stoplights

Vehicle Control

ABS (Antilock Brakes)
Traction
Electronic Stability
Corner Braking
EBD (Electronic Brake Force Distribution)

Driver Assistance

Park Distance - Front
Park Distance - Rear

Security

Central Locking - Key Proximity
Central Locking - Remote/Keyless
Data Dots - Part Identifiers
Engine Immobiliser
Comfort & Convenience

Climate

Climate Control

Air Quality

Pollen Filter

Driving

Cruise Control

Illumination

Courtesy Lamps - in Doors Front

Courtesy Lamps - in Doors Rear

Footwell Lamps - Front

Map/Reading Lamps - for 1st Row

Map/Reading Lamps - for 2nd Row

Key

Keyless Start - Key/FOB Proximity related

Start

Starter Button - Key/Fob Proximity

Armrests

Front (Driver & Passenger)

Sunvisor

Illuminated Vanity Mirrors Dual

Other

Ski Bag

Lights & Windows

Headlights

High Beam Auto Dipping

Active (Cornering/steering)

Automatic (light sensitive)

Bi-Xenon (for low & high beam)

Washers

Lights

Fog Lamps - Front

Power Windows

Front & Rear

Rear View Mirror

Electric Anti Glare

Wipers

Heated Washer Jets

Intermittent Wipers - Variable

Rain Sensor (Auto wipers)

Interior

Leather

Gear Knob

Steering Wheel

Trim (Incl. Seats, inserts)

Gloss Finish

Inserts

Seating

Front Row Seats

Height Adjustable Driver

Electric Seats

Drivers

Drivers with Memory

Driver with Electric Lumbar

Passenger

Passenger with Electric Lumbar

1st Row

2nd Row Seats

Split Fold

Rear Seats

Seat - Rear Opening for Skis/boot access

Instruments & Controls

Display

On-board Computer

Gauges

Tacho

Navigation

Compass

GPS (Satellite Navigation)

Navigation System - DVD Audio

Navigation System - DVD Video

Exterior

Body Coloured

Bumpers

Door Handles

Exterior Mirrors Full

Chrome Finish

Grille

Ringed Instruments

Mirrors

Electric - Heated

Body

Exhaust

Stainless Steel Dual System

Engine

Engine Description

Drive By Wire (Electronic Throttle Control)

Transmission & Drivetrain

Gearbox

Gear Shift Paddles behind Steering Wheel

Steering

Operation

Multi-function Steering Wheel

Performance

Steering Wheel - Sports

Power Steering

Steering Column

Tilt and Reach

Brakes

Front

Ventilated

Rear

Ventilated

Wheels & Tyres

Front Rim

17" Alloy Wheels

Spare Wheel

Tyres - Runflat